Materials Science

ME 274

Dr Yehia M. Youssef

Point Defects in Alloys

Two outcomes if impurity (B) added to host (A):

- Solid solution of B in A (i.e., random dist. of point defects)



OR



Substitutional solid soln.
(e.g., Cu in Ni)

Interstitial solid soln.
(e.g., C in Fe)

- Solid solution of B in A plus particles of a new phase (usually for a larger amount of B)



Second phase particle
--different composition
--often different structure.

Conditions for substitutional solid solution (S.S.)

- W. Hume – Rothery rule
  1. Δr (atomic radius) < 15%
  2. Proximity in periodic table
     - i.e., similar electronegativities
  3. Same crystal structure for pure metals
  4. Valency
     - All else being equal, a metal will have a greater tendency to dissolve a metal of higher valency than one of lower valency

Imperfections in Solids

Application of Hume–Rothery rules – Solid Solutions

1. Would you predict more Al or Ag to dissolve in Zn?

2. More Zn or Al in Cu?

Element	*Atomic Radius (nm)*	*Crystal Structure*	*Electro-nega-tivity*	*Valence*
Cu	0.1278	FCC	1.9	+2
C	0.071			
H	0.046			
O	0.060			
Ag	0.1445	FCC	1.9	+1
Al	0.1431	FCC	1.5	+3
Co	0.1253	HCP	1.8	+2
Cr	0.1249	BCC	1.6	+3
Fe	0.1241	BCC	1.8	+2
Ni	0.1246	FCC	1.8	+2
Pd	0.1376	FCC	2.2	+2
Zn	0.1332	HCP	1.6	+2

Table on p. 106, *Callister 7e.*

Imperfections in Solids

- Specification of composition
  - weight percent

$$C_1 = \frac{m_1}{m_1 + m_2} \text{ x } 100$$

m_1 = mass of component 1

  - atom percent

$$C_1' = \frac{n_{m1}}{n_{m1} + n_{m2}} \text{ x } 100$$

n_{m1} = number of moles of component 1

Line Defects

Dislocations:

- are line defects,
- slip between crystal planes result when dislocations move,
- produce permanent (plastic) deformation.

Schematic of Zinc (HCP):

- before deformation



- after tensile elongation



Adapted from Fig. 7.8, *Callister 7e.*

Imperfections in Solids

Linear Defects (Dislocations)

- Are one-dimensional defects around which atoms are misaligned

- Edge dislocation:
  - extra half-plane of atoms inserted in a crystal structure
  - **b** $\perp$ to dislocation line
- Screw dislocation:
  - spiral planar ramp resulting from shear deformation
  - **b** $||$ to dislocation line

Burger's vector, **b**: measure of lattice distortion

Imperfections in Solids

Edge Dislocation



Fig. 4.3, *Callister 7e.*

Motion of Edge Dislocation

- Dislocation motion requires the successive bumping of a half plane of atoms (from left to right here).
- Bonds across the slipping planes are broken and remade in succession.



Atomic view of edge dislocation motion from left to right as a crystal is sheared.

(Courtesy P.M. Anderson)

Imperfections in Solids

Screw Dislocation



Adapted from Fig. 4.4, *Callister 7e.*

Edge, Screw, and Mixed Dislocations



Adapted from Fig. 4.5, *Callister 7e.*

Imperfections in Solids

Dislocations are visible in electron micrographs

Adapted from Fig. 4.6, *Callister 7e.*

Dislocations & Crystal Structures

- Structure: close-packed planes & directions are preferred.



view onto two close-packed planes.

close-packed directions

close-packed plane (bottom) close-packed plane (top)

- Comparison among crystal structures:
  FCC: many close-packed planes/directions;
  HCP: only one plane, 3 directions;
  BCC: none

- Specimens that were tensile tested.



Mg (HCP)

Al (FCC)

Planar Defects in Solids

- One case is a twin boundary (plane)
  - Essentially a reflection of atom positions across the twin plane.



Adapted from Fig. 4.9, *Callister 7e.*

- Stacking faults
  - For FCC metals an error in ABCABC packing sequence
  - Ex: ABCABABC

Microscopic Examination

- Crystallites (grains) and grain boundaries. Vary considerably in size. Can be quite large
  - ex: Large single crystal of quartz or diamond or Si
  - ex: Aluminum light post or garbage can - see the individual grains
- Crystallites (grains) can be quite small (mm or less) – necessary to observe with a microscope.

Optical Microscopy

- Useful up to 2000X magnification.
- Polishing removes surface features (e.g., scratches)
- Etching changes reflectance, depending on crystal orientation.



crystallographic planes

Adapted from Fig. 4.13(b) and (c), *Callister 7e.* (Fig. 4.13(c) is courtesy of J.E. Burke, General Electric Co.

0.75mm

Micrograph of brass (a Cu-Zn alloy)

Optical Microscopy

Grain boundaries...

- are imperfections,
- are more susceptible to etching,
- may be revealed as dark lines,
- change in crystal orientation across boundary.

ASTM grain size number

$$N = 2^{n-1}$$

number of grains/in^2 at 100x magnification



(a)



(b)

Adapted from Fig. 4.14(a) and (b), *Callister 7e.* (Fig. 4.14(b) is courtesy of L.C. Smith and C. Brady, the National Bureau of Standards, Washington, DC [now the National Institute of Standards and Technology, Gaithersburg, MD].)

Optical Microscopy

- Polarized light
  - metallographic scopes often use polarized light to increase contrast
  - Also used for transparent samples such as polymers

Microscopy

Optical resolution ca. 10^{-7} m = 0.1 μm = 100 nm

For higher resolution need higher frequency

- – X-Rays? Difficult to focus.
- – Electrons
  - wavelengths ca. 3 pm (0.003 nm)
    - – (Magnification - 1,000,000X)
  - Atomic resolution possible
  - Electron beam focused by magnetic lenses.

Scanning Tunneling Microscopy (STM)

- Atoms can be arranged and imaged!



Carbon monoxide molecules arranged on a platinum (111) surface.



Photos produced from the work of C.P. Lutz, Zeppenfeld, and D.M. Eigler. Reprinted with permission from International Business Machines Corporation, copyright 1995.

Iron atoms arranged on a copper (111) surface. These Kanji characters represent the word “atom”.

Summary

- Point, Line, and Area defects exist in solids.
- The number and type of defects can be varied and controlled (e.g., *T* controls vacancy conc.)
- Defects affect material properties (e.g., grain boundaries control crystal slip).
- Defects may be desirable or undesirable (e.g., dislocations may be good or bad, depending on whether plastic deformation is desirable or not.)